



### In Situ Temperature Measurement Test Report

For

## LIGHT EFFICIENT DESIGN

# (Brand Name:N/A)

188 S. Northwest Highway Cary, IL 60013

# **LED** Lamp

Model name(s): LED-8030MXX-A

Remark : The letter "XX" on the model name represents the color temperature, "40" stand for 4000K, "57" stand for 5700K.

Representative (Tested) Model: LED-8030M40-A

Model Different: N/A

Test & Report By:

Jack Luo

Engineer: Jack Luo Date:May.31,2016 Review By:

Tommy Liang

Manager: Tommy Liang

Note: This report does not imply product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government.





### **Table of Contents**

1 General	3
1.1 Product Information	3
1.2 Standards or methods	
1.3 Equipment list	· · · · · · · 4
2.1 Ambient Condition	4
2.2 Temperature Stabilization	4
2.3 Thermocouples	5
2.4 Thermocouples contact	5
3.1 Test Data:	错误!未定义书签。
3.2 Test Photo:	6
3.3 Test Data of LED Driver:	错误!未定义书签。
3.4 Test Photo:	错误!未定义书签。





# 1 General

### **1.1 Product Information**

Brand Name	N/A
Model Number	LED-8030MXX-A
Luminaire Type	LED Lamp
Nominal Power	140W
Rated Initial Lamp Lumen	
Declared CCT	4000K,5700K
LED Manufacturer	Guangzhou Hongli Opto-Electronic Co., Ltd.
LED Model	HL-A-2835HW-S1-08-HR3
Sample Receipt Date	Apr.01,2016
Sample Number	GZE160347-G1

Photo









### **1.2 Standards or methods**

The following standards are partly or totally used or referenced for test:

No.	Name
ANSI/UL 1598:2008	Luminaires

### **1.3 Equipment list**

Equipment ID	Equipment Name	Last Calibration Date	Next Calibration Date
PF210	Power Meter	2015-07-01	2016-06-30
ST-R-181A	Temperature Tester	2015-07-01	2016-06-30

# 2 Test conducted and method

### 2.1 Ambient Condition

Test was conducted in an ambient temperature of  $25\pm5$  °C. Ambient temperature variations above or below 25 °C was subtracted from or added to temperatures recorded at points on the luminaire. The ambient temperature was measured by a thermocouple which was immersed in 15ml of mineral oil in a glass container.

### 2.2 Temperature Stabilization

Temperatures were measured after they have stabilized when the test has been running for a minimum of 7.5 hours, or the test has been running for a minimum of 3 hours and three successive reading taken at 15 minutes intervals are with  $1^{\circ}$  of another and are not rising.

Laboratory: Standard-Tech Co. Ltd Testing Center NVLAP CODE: 201011-0 Report Format Number STD/QR4918-A/0 Address : Standard-Tech Building, No.6 Guanhong Road,Guangzhou Science City, Guangzhou 510663, China Tel: 8620-3229 0320 Fax: 8620-32290422 <u>http://www.standard-tech.com</u> 4 / 7





### **2.3 Thermocouples**

Type J thermocouple was used for temperature measurement. The thermocouple was 0.05mm2(30AWG), and complied with the requirements specified in ASTM MNL 12 and limits of error specified in NIST ITS 90 and ISA MC96.1.

### 2.4 Thermocouples contact

Thermocouples were in contact with the TMP LED location described in LM-80 test report. In order to gain the maximum temperature, if appropriate, more than one thermocouple were contact in these locations. For details information, please refer to clause 3.3 for the photo of thermocouple contact.





# **3 Test Results**

Test date		2016-04-24	Т	est Ambient	25.1 °C		
Samp	le No.		LED Package Model				
GZE160	GZE160347-G1			HL-A-2835HW-S1-08-HR3			
LED driver of Each La	mp	Output voltage	e V Measured LED working current (Max.) m/				
1		71.6			49.2		

### 3.1 Test Data:

Input	Vol.	120.0V	Input Curr	ent	1.2	235A	Input Wa	attage	144.4V	V sta	Temperature abilization time:	500 min
No.	Τe	emperat	ure (°C)	No.			Temperature (°C)		No.	Temperature (°C)		
	Moor	sured	Corrected			Measured		Corr	ected		Measured	Corrected
	Ivieas	suled	at 25°C					at 2	5°C			at 25°C
1	54.3		54.2	3		52.9		52.8		5	54.0	53.9
2	53.4		53.3	4		53.7		53.6		6	53.3	53.2
The highest in-situ measured temperature LED is 54.2°C												

### **3.2 Test Photo:**

Ts Position:







Thermocouple Location on Temperature Measurement Point (TMP):



# Results

Time (t) at which to estimate lumen maintenance (hours):	36,000		
Lumen maintenance at time (t) (%):	82.93%		
Reported L70 (hours):	>54000		

\*\*\*\*\*\* END OF THE TEST REPORT\*\*\*\*\*

Laboratory: Standard-Tech Co. Ltd Testing Center NVLAP CODE: 201011-0 Report Format Number STD/QR4918-A/0 Address : Standard-Tech Building, No.6 Guanhong Road,Guangzhou Science City, Guangzhou 510663, China Tel: 8620-3229 0320 Fax: 8620-32290422 <u>http://www.standard-tech.com</u> 7 / 7